

Fitness Certificate 2023 – 2024

1. Name of the Officer : Aji C.T.
 2. Name of the School : De Paul Public School, Thodupuzha
 3. Location with name of Ednl.Dist. : 6 storied RCC structural building, Total plinth area 3010.53m² (excluding 3rd and 4th floor, roof)
 4. Classification of building as specified in column 4 of the application for fitness certificate :
: 2023-2024 Academic Year
 5. Period for which the certificate issued : 2023-2024 Academic Year
 6. Nature of defect if any :
 - a) Foundation and basement : { Nil, Structure is sound under normal weather condition.
 - b) Superstructure : {
 - c) Doors and windows : }
 - d) Roof : }
 - e) Flooring : }
 - f) Miscellaneous (Cracks) : }
 7. Any major defects noticed which Will render the building unsafe in any Manner. : No. major defects noticed
 8. Whether the maintenance work have been done : Yes 2022-May
Accessed area only
- Notes :-
- 1) The stability of the structure should be examined also with reference to location altitude, intensity of with exposure to flood etc.
 - 2) Any additional observations if deemed necessary for the certificate may furnished separately with the certificate.

CERTIFICATE

Certified that the school was inspected by me on. 10/10/22.....and found to be fit/unfit to conduct classes, for the period up to ...2022-24.....for the reason stated above.

Place: Thodupuzha

Date: 10/10/22




C/T
ASSISTANT ENGINEER
LSGD. LID & EW